


# Electrical Wiring



Always completely cut through any heating stripe



Electrically live edges of heating stripes must be insulated

